

We saw this natural avalanche from afar. It was NE aspect and likely failed on a layer of surface hoar 1-1.5' deep. The Madison Valley is in the background. Photo: GNFAC

Advisory Region
Northern Madison
Longitude
-111.51W
Latitude
45.21N

Avalanche Details: Natural avalanche near Cedar Mtn.
Forecast link: GNFAC Avalanche Forecast for Tue Mar 31, 2020
Northern Madison, 2020-03-30